

DAILY STATUS REPORTPrepared By: Luke Buquicchio

WEATHER	Snow		Rain		Overcast		Partly Cloudy		Bright Sun	x
TEMP.	< 32		32-50		50-70	x	70-85		>85	

NYSDEC Spill No.	25-08914	MOSF#	2-2640	Date:	8/24/2026
Project Name:	Former Goldwater Memorial Hospital MOSF 5 East Main Street Roosevelt Island, Manhattan, New York 10044		Wind: Fair wind conditions from NE to SW		

Consultant: Luke Buquicchio - Preferred Environmental Services Eileen Cipollone – Restoration Conservation Advisement	Safety Officer:
General Contractor: Statewide Demolition Corporation Subcontractors:	Site Manager/ Supervisor: Peter Musso
Work Activities Performed (Since Last Report): - Statewide imported fifteen (15) loads of clean fill from Hunter's Point. - Statewide backfilled and compacted clean fill in Grid 4. - Statewide placed a demarcation barrier in Grid 4.	
Working In Grid #: 4	
Stabilized Construction Entrance inspected: Yes / No Repair Needed: Yes / No	
<u>Truck Inspection Station/Decontamination Pad</u> Trucks inspected and debris removed: Yes / No	
<u>Sump Area of Decontamination Pad</u> Any Run-off leaving Sump: Yes / No Sediment building placed in drums: Yes / No # of drums to date: 0	
Samples Collected (Since Last Report): N/A	
Air Monitoring (Since Last Report): Air Monitoring was conducted during intrusive work activities. Prestart Conditions – PID = 0.0 ppm, Dust = 0.044 mg/m ³ High Conditions – PID = 0.0 ppm, Dust = 0.047 mg/m ³ (see below)	

CAMP Log

8/24/26

Date: 8/24/26 Enter Site Name: Former Goldwater Memorial Hospital MOSF Daily Activity

Air Monitoring Log Consultant: EILEEN CIPOLLONE

Time	Upwind Dust (ug/m3)	Upwind PID (ppm)	Downwind Dust (ug/m3)	Downwind PID (ppm)
6:47	0.044	0.0	1.037	0.0
7:00	0.016		0.028	0.0
7:15	0.015		0.024	0.0
7:30	0.017		0.026	0.0
7:45	0.021		0.024	0.0
8:00	0.026		0.026	0.0
8:15	0.020		0.025	0.0
8:30	0.020		0.031	0.0
8:45	0.019		0.038	0.0
9:00	0.024		0.037	0.0
9:15	0.027		0.036	0.0
9:30	0.029		0.036	0.0
9:45	0.026		0.035	0.0
10:00	0.026		0.038	0.0
10:15	0.023		0.038	0.0
10:30	0.021		0.041	0.0
10:45	0.021		0.046	0.0
11:00	0.020		0.044	0.0
11:15	0.027		0.040	0.0
11:30	0.028		0.038	0.0
11:45	0.025		0.047	0.0
12:00	0.034		0.032	0.0
12:15	0.023		0.038	0.0
12:30	0.038		0.041	0.0
12:45	0.042		0.032	0.0
1:00	0.036		0.035	0.0
1:15	0.020		0.030	0.0
1:30	0.021		0.031	0.0
1:45	0.026		0.023	0.0
2:00	0.019		0.021	0.0
2:15	0.024		0.030	0.0
2:30	0.022		0.023	0.0
2:45	0.019		0.034	0.0
3:00	0.029		0.029	0.0
3:15	0.019		0.026	0.0
3:30	0.020		0.020	0.0

67°F

Sunny
wind from NE → SW

Downwind initially
high readings
Due to
Diesel exhaust
of excavator
moved 10 feet
Resolved

