

**DAILY STATUS REPORT**Prepared By: Luke Buquicchio

|         |      |  |       |  |          |   |               |  |            |   |
|---------|------|--|-------|--|----------|---|---------------|--|------------|---|
| WEATHER | Snow |  | Rain  |  | Overcast |   | Partly Cloudy |  | Bright Sun | x |
| TEMP.   | < 32 |  | 32-50 |  | 50-70    | x | 70-85         |  | >85        |   |

|                  |                                                                                                                    |       |                 |       |           |
|------------------|--------------------------------------------------------------------------------------------------------------------|-------|-----------------|-------|-----------|
| NYSDEC Spill No. | 25-08914                                                                                                           | MOSF# | 2-2640          | Date: | 8/31/2026 |
| Project Name:    | Former Goldwater Memorial Hospital<br>MOSF<br>5 East Main Street<br>Roosevelt Island, Manhattan, New York<br>10044 |       | Wind: NNE 4 mph |       |           |

|                                                                                                                                                                                                                                                                                                               |                                                 |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|
| Consultant:<br>Luke Buquicchio - Preferred Environmental Services<br>Eileen Cipollone – Restoration Conservation Advisement                                                                                                                                                                                   | Safety Officer:                                 |
| General Contractor:<br>Statewide Demolition Corporation<br>Subcontractors:                                                                                                                                                                                                                                    | Site Manager/ Supervisor:<br><b>Peter Musso</b> |
| Work Activities Performed (Since Last Report): <ul style="list-style-type: none"> <li>Statewide imported nineteen (19) loads of clean fill from Hunter's Point.</li> <li>Statewide backfilled and compacted clean fill.</li> <li>Statewide sprayed water over the site as needed to mitigate dust.</li> </ul> |                                                 |
| Working In Grid #: 2, 3, 4                                                                                                                                                                                                                                                                                    |                                                 |
| Stabilized Construction Entrance inspected: <b>Yes</b> / No      Repair Needed: Yes / <b>No</b>                                                                                                                                                                                                               |                                                 |
| <u>Truck Inspection Station/Decontamination Pad</u><br>Trucks inspected and debris removed: <b>Yes</b> / No                                                                                                                                                                                                   |                                                 |
| <u>Sump Area of Decontamination Pad</u><br>Any Run-off leaving Sump: Yes / <b>No</b><br>Sediment building placed in drums: Yes / <b>No</b><br># of drums to date: 0                                                                                                                                           |                                                 |
| Samples Collected (Since Last Report): N/A                                                                                                                                                                                                                                                                    |                                                 |
| Air Monitoring (Since Last Report):<br>Air Monitoring was conducted during intrusive work activities.<br>Prestart Conditions – PID = 0.0 ppm, Dust = 0.017 mg/m <sup>3</sup><br>High Conditions – PID = 0.0 ppm, Dust = 0.022 mg/m <sup>3</sup> (see below)                                                   |                                                 |

# CAMP Log

Date: 8/31/26 Enter Site Name: Former Goldwater Memorial Hospital MOSE Daily Activity

Consultant: Eileen Cipollone

| Time  | Upwind Dust (ug/m3) | Upwind PID (ppm) | Downwind Dust (ug/m3) | Downwind PID (ppm) |
|-------|---------------------|------------------|-----------------------|--------------------|
| 7:00  | 0.048               | 0.0              | 0.017                 | 0.0                |
| 7:15  | 0.015               |                  | 0.014                 | 0.0                |
| 7:30  | 0.014               |                  | 0.014                 | 0.0                |
| 7:45  | 0.015               |                  | 0.013                 | 0.0                |
| 8:00  | 0.015               |                  | 0.014                 | 0.0                |
| 8:15  | 0.017               |                  | 0.014                 | 0.0                |
| 8:30  | 0.016               |                  | 0.013                 | 0.0                |
| 8:45  | 0.015               |                  | 0.014                 | 0.0                |
| 9:00  | 0.015               |                  | 0.014                 | 0.0                |
| 9:15  | 0.015               |                  | 0.015                 | 0.0                |
| 9:30  | 0.014               |                  | 0.014                 | 0.0                |
| 9:45  | 0.015               |                  | 0.018                 | 0.0                |
| 10:00 | 0.015               |                  | 0.016                 | 0.0                |
| 10:15 | 0.016               |                  | 0.016                 | 0.0                |
| 10:30 | 0.017               |                  | 0.015                 | 0.0                |
| 10:45 | 0.015               |                  | 0.017                 | 0.0                |
| 11:00 | 0.017               |                  | 0.023                 | 0.0                |
| 11:15 | 0.024               |                  | 0.023                 | 0.0                |
| 11:30 | 0.025               |                  | 0.023                 | 0.0                |
| 11:45 | 0.014               |                  | 0.018                 | 0.0                |
| 12:00 | 0.016               |                  | 0.017                 | 0.0                |
| 12:15 | 0.015               |                  | 0.018                 | 0.0                |
| 12:30 | 0.016               |                  | 0.017                 | 0.0                |
| 12:45 | 0.015               |                  | 0.018                 | 0.0                |
| 1:00  | 0.015               |                  | 0.019                 | 0.0                |
| 1:15  | 0.017               |                  | 0.019                 | 0.0                |
| 1:30  | 0.017               |                  | 0.022                 | 0.0                |
| 1:45  | 0.015               |                  | 0.019                 | 0.0                |
| 2:00  | 0.017               |                  | 0.021                 | 0.0                |
| 2:15  | 0.019               |                  | 0.018                 | 0.0                |
| 2:30  | 0.018               |                  | 0.019                 | 0.0                |
| 2:45  | 0.019               |                  | 0.021                 | 0.0                |
| 3:00  | 0.015               |                  | 0.020                 | 0.0                |
| 3:15  | 0.021               |                  | 0.020                 | 0.0                |

Temp 70°  
 Cloudy  
 Wind Direction NNE  
 4 mph  
 \*working on south side of  
 site - NO ACCESS TO SET UP  
 UW

